

Old Masters®

Since 1953



1900 Albany Place SE
P.O. Box 286
Orange City, IA 51041

800-737-3436 Fax 712-737-3893
www.oldmastrs.com

PRODUCT INFORMATION

WIPING STAIN CLASSICS

PRODUCT NO.	128 through 130 Series
GENERIC TYPE	Penetrating/decorator oil-based stain
COLOR	3 Ready-Mixed colors
GLOSS	Not Applicable
SOLIDS BY WEIGHT	36.6 - 45.2%
SOLIDS BY VOLUME	29.2 - 30.2%
V.O.C.	550 grams/liter
THEORETICAL COVERAGE @ 1 MIL DFT	Not Applicable
COVERAGE @ RECOMMENDED DFT	Not Applicable
RECOMMENDED DFT PER COAT	Not Applicable
WEIGHT PER GALLON	7.3 - 8.5
FLASH POINT	102°F Tag Closed Cup
USE	For interior use on bare wood as a penetrating semi-transparent stain or as a glaze in the woodgraining or faux-finishing.
VISCOSITY AT 77°F	300 to 500 cps using Brookfield viscometer
AVERAGE DRY TIME AT 70°F & 50% R.H.	Approximately 10 hours, depending on humidity, temperature and use of product.
RECOMMENDED THINNER	Do Not Thin
APPLICATION	Apply with brush, lint-free cloth, pad applicator, or sprayer. See label for specific surface applications.
SURFACE PREPARATION	The Surface must be free from dirt, wax, and grease. Wood surfaces should be sanded smooth.
CLEAN UP	Mineral Spirits
COMPOSITION	By colors upon request - colors are: Natural Walnut 128 Pecan 129 American Walnut 130

FOR THE LOVE OF WOOD®

Interior Wood Stains, Clears, Removers & Miscellaneous Sundries



PRODUCT INFORMATION

WIPING STAIN CLASSICS

DESCRIPTION: OLD MASTERS® WIPING STAIN is a full-bodied, oil-based, semi-transparent stain that provides better color control, beauty and richness. Because of its ease in application, consistent results and forgiveness in use, it is the ideal stain for the do-it-yourself enthusiast and the professional. It is the most efficient stain manufactured to make different surfaces uniform and is ideal for refinishing projects. Its thick, rich formula allows it to achieve limitless decorating possibilities when used as either a stain or as a glaze over any of the Old Masters® Graining Bases.

MIXING SPECIAL COLORS: Special colors may be created by adding up to 10 ounces of universal colorant per gallon or by intermixing any WIPING STAIN colors. Create Santa Fe pastel colors by tinting Pickling White WIPING STAIN. (Formulas available upon request.) Natural WIPING STAIN may be used to lighten a WIPING STAIN color in any proportion or as a tint base for ultimate color selection. The amount of colorant added may affect its performance and extend the dry time.

THINNING: Do not thin. Use as packaged.

SURFACE PREPARATION: The secret to successful applications is a properly prepared surface. All surfaces must be sound, dry and free from dust, dirt, wax or grease. Surface defects should be repaired with an appropriate patching material.

WARNING! If you scrape, sand or remove old paint, you may release lead dust. LEAD IS TOXIC. Contact the National Lead Information Hotline at 1-800-424-LEAD or log on to www.epa.gov/lead.

APPLICATION ON BARE WOOD (used as a **stain**): Color of stain will vary depending on wood type and porosity and the method of application. Always test stain in an inconspicuous area. Stir well before and during application for even distribution of color. After cleaning wood surface, sand with #120 or

#180 sandpaper until smooth, then remove sanding dust. Apply stain liberally with brush, lint-free cloth or spray until surface is completely wet. Allow to penetrate for 5 to 15 minutes. Then wipe with a soft cloth, first across the grain, then with the grain. For a darker color, restain when first coat is dry. For a lighter color, wipe with a cloth dampened with paint thinner before the stain has dried. Before applying a clear finish, allow the stain to dry thoroughly.

APPLICATION OVER GRAINING BASE (used as a **glaze**): Apply to thoroughly dry paint with cheesecloth or brush using long, smooth strokes for simulated woodgraining, or blend gently from edges for other effects. Allow the stain to set up approximately 5 to 10 minutes, then dry brush to subdue or blend. Allow stain to dry thoroughly (usually 12 hours or longer, depending on humidity and drying conditions). Apply a clear finish when stain is thoroughly dry. We do not recommend a lacquer-type finish over a glaze application.

SPREADING RATE: Approximately 500 square feet per gallon. Spreading rate will vary significantly depending on application method and condition of wood.

DRYING TIME: Approximately 10 hours, depending on humidity, temperature and use of product (as a stain or glaze). WIPING STAIN can be topcoated after 12 hours, but stain must be thoroughly dry.

CLEANUP: Use mineral spirits or paint thinner. To avoid spontaneous combustion during temporary storage, soak soiled rags and waste immediately after use in a water-filled, closed metal container.

RECOMMENDED FINISH COAT: We recommend Old Masters® clear finishes. However, our WIPING STAIN can be topcoated with most clears.

MAX. VOC: 550 grams/liter (4.6 lbs/gal)

Contains: Mineral Spirits, Kerosene and Crystalline Silica. VAPOR HARMFUL. MAY AFFECT THE BRAIN OR NERVOUS SYSTEM CAUSING DIZZINESS, HEADACHE OR NAUSEA. CAUSES NOSE, THROAT AND SKIN IRRITATION. NOTICE: Reports have associated repeated and prolonged occupational overexposure to solvents with permanent brain and nervous system damage. Intentional misuse by deliberately concentrating and inhaling the contents may be harmful or fatal. Cancer hazard. Contains Crystalline Silica, which can cause cancer. Risk of cancer depends on duration and level of exposure to dust generated from sanding surfaces or spray mists. Overexposure may cause lung and kidney damage. Keep away from heat, sparks and flame. VAPORS MAY CAUSE FLASH FIRE. Do not smoke. Extinguish all flames and pilot lights and turn off stoves, heaters, electric motors and other sources of ignition during use and until all vapors are gone. Prevent buildup of vapors by opening all windows and doors to achieve cross-ventilation. **Use only with adequate ventilation.** Do not breathe dust, vapors or spray mist. Ensure fresh air entry during application and drying. If you experience eye watering, headache or dizziness or if air monitoring demonstrates vapor/mist levels are above applicable limits, wear an appropriate, properly fitted respirator (NIOSH/MSHA-approved) during and after application. Avoid exposure to dust by wearing an appropriate (NIOSH-approved) particulate respirator during application, sanding and cleanup. Follow respirator manufacturer's directions for respirator use. Avoid contact with eyes, skin and clothing. Wash thoroughly after handling. **KEEP OUT OF REACH OF CHILDREN.** **First Aid:** In case of eye contact, flush immediately with plenty of water for at least 15 minutes and get medical attention immediately; for skin, wash thoroughly with soap and water. If you experience difficulty in breathing, leave the area to obtain fresh air. If continued difficulty is experienced, get medical attention immediately. If swallowed, do not induce vomiting. Get medical attention immediately. If spilled, contain spilled material and remove with inert absorbent. Dispose of contaminated absorbent, container and unused contents in accordance with local, state and federal regulations.

Limited Warranty Since Old Masters® does not control the application of its products, nor the condition of the surfaces to which they are applied, a Limited Warranty is provided. If the products do not perform as specified, for whatever reason, Old Masters® liability will under no circumstances exceed replacement of the product.

OLD MASTERS®
1900 ALBANY PLACE SE
ORANGE CITY, IA 51041